Idaho PUC Pipeline Safety Inspection Summary

Inspector(s): Ulmer/Perkins			Date(s):	7-Jan-20
Company/Owner:	Intermountain Gas Company		Unit/OPID:	8160
Inspection Type & Time (1 day) Total			Inspection Days:	2
Standard: Construction: 2 Training: (T)(D) Integrity Management: Incident: M/M: Follow-up: OQ: Damage Prevention: D&A:				
,		24		
Inspection Summary				
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.				
Observed a Dasco crew installing a new service. The crew lead continually used backhoe when digging within 2' of the pipe, additionally joiner did not clean pipe correctly prior to pushing into continental fitting. Pressure tested the service and tied it in. Typed up report Areas observed during this project were: Excavating, Line locating, Pressure testing, Backfilling and Joining				
Attachments: IPUC Form 4 Construction Inspections Das-co Daily Itineraries located in file for the project. OQ's for all observed employees are located in file for the project.				
Corrective Action Required:		w-up Required: Y	es No	Х
Yes No	X	7	by (date):	
Inspector (Lead): Bruce Perkins	12 2 E/V.	As.	Date: 1/7/2020	
Reviewer:	11/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1	77	Date:	
Neviewei.			Date:	T. 2020